




# 1965 FORD "K" CODE HIPO MUSTANG CONVERTIBLE

With over half a million cars sold in its first year, the 1965 Mustang created the "pony car craze." Of those less than 1% were produced with "K" Code engines and very few of those were convertibles. According to the HiPo Mustang registry, Ford produced nearly 1.7 million Mustangs from '65-'67, but only 13,500 were HiPo 289-equipped. In 1965, only 181 HiPo Mustang convertibles were produced.



Powered by the 289 CI (271 HP) "K" Code V8 engine built by Ford for Carroll Shelby's AC Cobra in 1963.



Four-speed Toploader manual transmission







The Ford Mustang was introduced at the 1965 World's Fair in the Walt Disney Imagineering-designed pavilion that featured a "Magic Skyway" animatronic ride.



Uniquely badged with High Performance 289



Concours restored in the Gary Thomas Collection with original factory markings and new old stock (NOS) parts.




Disc brakes





# Mustang



## 1965 REGISTERED OWNER'S MANUAL

30 Pages  
**CONTENTS**

	PAGE
• Registered Owner Plan.....	1
• Warranty.....	2
• Maintenance.....	13
• Controls.....	33
• Accessories.....	49
• Operation.....	53
• Ford Quality Car Care.....	68



# Keep the Total Performance that's built into your 1965 MUSTANG...

## ALWAYS USE GENUINE FORD REPLACEMENT PARTS


You can keep your new Mustang running like new when you insist on Genuine FoMoCo, Autolite, and Rotunda Replacement Parts . . . precision-made parts engineered to the same high quality standards

established for Ford original equipment. This is especially important if you are to enjoy the maximum benefits of Ford's more care-free Twice-a-Year Maintenance.

## ALWAYS BRING YOUR MUSTANG BACK HOME FOR SERVICE

Nobody cares for your Mustang like your Ford Dealer. He knows your Mustang best, so it stands to reason that he can service it best. His *Ford Quality Car Care* service specialists have the special tools and equipment, genuine parts and Ford know-how

to keep your new car in top operating condition. Regular service maintenance every 6 months or 6,000 miles will help keep your Mustang looking younger, running better . . . save you time and money in the long run.

A PRODUCT OF  MOTOR COMPANY



**AUTOLITE**





BODY COLOR TRIM DATE DSO AXLE TRANS

76A J 25 01J 65 8 5

VEHICLE WARRANTY NUMBER

5R08K133254

Ford®

NOT FOR TITLE OR  
REGISTRATION PURPOSES

THIS VEHICLE IS MANUFACTURED UNDER UNITED STATES  
AND FOREIGN PATENTS AND PATENT APPLICATIONS

A PRODUCT OF



MOTOR COMPANY

MADE IN U.S.A.



POLICY NUMBER

EFFECTIVE DATE

1307 419-F17-36

JUN-17-76

NAMED  
INSURED

LIMESTALL, JAMES D

VEHICLE, YEAR, MAKE & COVERAGES (DEFINED IN POLICY)

65 MUSTANG AB C D U

HOW TO IDENTIFY YOUR COVERAGES-See policy for full name and variations-not all coverages available in all states.

A,B -Bodily Injury/Property Damage

C,M -Medical Payments

F,G -Personal Injury (Different Name in Some States.)

N -Property Protection (Different Name in Some States.)

D -Comprehensive

F,G,J -Collision

L -Combination Physical Damage

H -Emergency Road Service or Towing and Labor

R,R1 -Rental Reimbursement

U -Uninsured Motor Vehicle

W -Underinsured Motorist (Minn.)

S,T -Death/Disability

Z -Loss of Earnings

# COLORADO REGISTRATION/OWNERSHIP TAX RECEIPT

TYPE	PLATE	TAB/VAL	VIN	EXPIRE				
PAS-COL	644VKT	M007550	5R08K133254	09/2014				
TITLE	YR	MAKE	BODY	CWT/PAS	T/C	FLEET#	FUEL	PREV EXP
12P369856	1965	FOR	CV	27	C		G	01/2003
PUR. DATE	PUR. PRICE	ORIGINAL TAXABLE VALUE		BUS. DATE	CO #	UR/CODE		
11/01/1978	0.00	2,402		09/02/2009	07	U 0013		
EM. FEE	TITLE FEE	PRIOR O.T.	OWN TAX	LIC. FEE	ROAD FEE	BRIDGE FEE		
0.00	0.00	6.00	15.00	255.42	<b>23.00</b>	<b>9.00</b>		
RTD TAX	COUNTY TAX	CITY/DIST TAX	STATE TAX	SPECIAL FEE	OTHER FEE			
0.00	0.00	0.00	0.00	0.00	0.00			
UNIT #	GVW	MILES	HI GVW	HC DATE				

OWNER NAME/MAILING ADDRESS

**\*FEES IN BOLD INCLUDED IN LIC FEE**

SLAUGHTER RICHARD

P/03041996/E/031997

122 KOLAR CT

ERIE

CO 80516

**SIGNATURE  
REQUIRED  
ON REVERSE  
SIDE.**

VALIDATION

TOTAL

PAID BOULDER

14 09/02/2009 090916MMV R04

A

276.42 PL

MOTOR VEHICLE INSURANCE IS COMPULSORY IN COLORADO, NON-COMPLIANCE IS A MISDEMEANOR TRAFFIC OFFENSE



RE: richards\_777 sent a message about Ford : Mustang #290529423918

Richard Slaughter

to:

gary\_thomas

02/22/2011 10:47 AM

Cc:

""Richard Slaughter""

Show Details

Security:

Some images were prevented from loading. Show Images

History: This message has been forwarded.

Gary,

Congrats, you now own a great k code 1965 mustang. I can be reached at 303-828-4173. The car is in Erie Colorado.

My bank account number is Chase Bank account:

Volt Mustangs Inc.

routing # 102001017

Acc # 638967586

I Richard Slaughter 122 Kolar Court Erie Co 80516 have sold a 1965 Mustang convertible to Gary Thomas. The vehicle VIN number 5R08K133254. The CO title num 12P369856.

Mr. Thomas is responsible for arranging all shipping storage/handling of the car once payment is made.

Thanks


Richard Slaughter

**From:** eBay Member: gary32ford [mailto:member@ebay.com]

**Sent:** Tuesday, February 22, 2011 5:37 AM

**To:** rslaughter@compuserve.com

**Subject:** Re: richards\_777 sent a message about Ford : Mustang #290529423918



eBay sent this message to Richard Slaughter (richards\_777).

Your registered name is included to show this message originated from eBay. Learn more.

**Buyer has responded to your question about this item**

Do not respond to the sender if this message requests that you complete the transaction outside of eBay. This type of offer is against eBay policy, may be fraudulent, and is not covered by buyer protection programs. Learn More.

Dear richards\_777,


Sir,

I will send you a wire transfer if that will work.

Please email me directly and give me your number - will give you a call.

Thanks,

Click "respond" to reply through Messages, or go to your email to reply





Gary 832-603-2279  
gary\_thomas@eogresources.com

Thanks!

- gary32ford

From: richards\_777  
To: gary32ford  
Subject: richards\_777 sent a message about Ford : Mustang # 290529423918  
Sent Date: Feb-21-11 07:34:32 PST

**Dear gary32ford,**

Gary32Ford,  
I've never sold a car on ebay. I'm not sure exactly how to arrange payment shipping etc. I expect the money needs to be held in escrow until the car is shipped. Since you live in TX maybe you want to pick up the car yourself?

- richards\_777

Ford : Mustang

Ford : Mustang

Item Id: 290529423918

End time: Feb-21-11 07:27:54 PST

Buyer:

gary32ford (662 )

100.0% Positive Feedback

Member since Nov-06-03 in United States

Location: TX, United States

Listing

Status:

This message was sent while the listing was **closed**.

**Marketplace Safety**

**Tip**

- Keep your money safe - never pay for items with cash or instant money transfer services, such as Western Union or MoneyGram. In the past some sellers have exploited these payment methods in order to defraud buyers, so eBay has banned them from the site.
- Received a Second Chance Offer email? Double check that it's genuine: Second Chance Offer emails come directly from eBay and are shown in your My Messages.
- Trade safely. Beware of anyone who contacts you about buying or selling outside of eBay. When you trade outside of eBay, you're not able to leave feedback or take advantage of protection programs and case resolution tools available on eBay. Report an inappropriate email.
- eBay helps guard your privacy and online safety when you use our messaging tools. If you and the member you're contacting haven't bought or sold from each other recently, our tools may make both of your email addresses anonymous.





# VEHICLE INSPECTION REPORT

00866188

**COM**

## STATE OF COLORADO RESULTS

Overall Result	Emissions	Evaporative Systems	Equipment Inspection	Smoke	CFC's	Recall	OBD Codes	Total Amount Paid
FAIL	FAIL			PASS	N/A		N/A	15.00

### VEHICLE INFORMATION

VIN	STATE	LICENSE PLATE	YEAR	MAKE	ODOMETER	
5R08K133254	CO	XXXX3254	1965	FORD	65963	
PROGRAM	INSPECTOR #	LANE #	STATION #	START TIME	END TIME	DATE
E	00093	05	5001E	18:46:20	18:58:15	07-DEC-1995

### CONSUMER INFORMATION

Your vehicle has failed to comply with required State regulations for emissions inspection. All items listed as failure must be addressed prior to your next inspection. See the box titled "IF YOUR VEHICLE FAILED THE INSPECTION" for further instructions. If your vehicle failed emissions, see the box titled "POSSIBLE CAUSES FOR EMISSIONS FAILURE" for further instructions.

### EMISSIONS TEST INFORMATION

### EVAPORATIVE SYSTEMS TEST INFORMATION

	2500	IDLE	LIMITS	RESULTS		PRESSURE	PURGE	FUEL CAP RESULTS
HC PPM	1152.4	1658.3	1000.0	FAIL	UNITS	N/A	N/A	PASS
CO %	7.44	11.97	5.50	FAIL	LIMITS	N/A	N/A	
CO2 %	8.3480	6.8953			READINGS	N/A	N/A	
RPM	2525	725	1350	OK	RESULTS	N/A	N/A	

### EQUIPMENT INSPECTION INFORMATION

- Catalytic Converter -
- Fuel Filler Restrictor -
- Air Injection System -
- Oxygen Sensor -
- Check Engine Light - N/A

### IF YOUR VEHICLE PASSED OR WAS ISSUED A WAIVER

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If you are renewing your registration by mail, follow the instructions regarding the renewal process located on the back side of your renewal notice. If you are renewing your registration in person, the Certificate of Emissions Control must accompany all supporting documents at the time of registration. If the Certificate of Emissions Control is lost, a new inspection is required at the owner's/operator's expense.

### IF YOUR VEHICLE FAILED THE INSPECTION

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If your vehicle failed its first inspection, you are entitled to one free reinspection within 10 calendar days if returned to the same independent inspection station. If the first inspection was performed at an Envirotec center, the reinspection can be performed at any one of Envirotec's centers. The information recorded on this "VEHICLE INSPECTION REPORT" is extremely valuable to a repair technician when having your vehicle repaired. The "VEHICLE REPAIR FORM", (VRF), located on the back must be completed by the person performing the repairs. The VRF must also accompany the vehicle at the time of reinspection. If your vehicle fails the reinspection you may be entitled to a waiver. Waiver eligibility information is available at the inspection stations or by calling the Department of Revenue at (303) 572-5603.

### POSSIBLE CAUSES FOR EMISSION FAILURE

HIGH CO READINGS	HIGH HC READINGS	HIGH NOx READINGS
A. Incorrect air fuel mixture B. Dirty air cleaner, choke or carb./fuel injection C. Carburetor float level improperly adjusted D. Inoperative air pump E. Diluted lubricating oil F. Soaked fuel evaporative canister	A. Defective points/electronic ignition B. Open plug wire or fouled spark plug C. Vacuum leak D. Incorrect air/fuel mixture E. Inoperative air pump F. Incorrect ignition timing	A. Inoperative EGR system B. Incorrect ignition timing C. Incorrect air/fuel mixture D. Low octane fuel rating E. High combustion temperature F. Excessive carbon deposits

### OFFICIAL USE ONLY

TST: 1 FEE: 15.00 LAT: 0.00 TAX: 0.00 DIS: 0.00  
 CSH: 0.00 CHK: 15.00 CDT: 0.00 CPN: 0.00  
 IN2: 10723 IN3: 10523 CYL: 8 RMON: 12 RYR: 1995 GVW: NVW: DSP: 4.3 FUL: GAS  
 TVFY: A73D RVFY: 240C VVFY: 0F87 SNV: SMON:  
 SYR: OCT: 12 REC: MAK: FORD MDL: MUSTANG VTY: P TRA: A DRV: R ABS: N 2STK: N  
 TRC: N WMB: DEX: Y ECH: N EYR:  
 EFAW: HHC: 1152.4 HCO: 7.44  
 IHC: 1899.8 ICO: 11.44  
 ERES: F ORES: P PRES: IWVfy: 2B3C







# VEHICLE INSPECTION REPORT

00861942

## STATE OF COLORADO RESULTS

Overall Result	Emissions	Evaporative Systems	Equipment Inspection	Smoke	CFC's	Recall	OBD Codes	Total Amount Paid
FAIL	FAIL			PASS	N/A		N/A	15.00

### VEHICLE INFORMATION

VIN	STATE	LICENSE PLATE	YEAR	MAKE	ODOMETER	
5R08K133254	CO	XXXX3254	1965	FORD	66009	
PROGRAM	INSPECTOR #	LANE #	STATION #	START TIME	END TIME	DATE
E	00083	04	5001E	13:06:19	13:16:4	26-DEC-1995

### CONSUMER INFORMATION

Your vehicle has failed to comply with required State regulations for emissions inspection. All items listed as failure must be addressed prior to your next inspection. See the box titled "IF YOUR VEHICLE FAILED THE INSPECTION" for further instructions. If your vehicle failed emissions, see the box titled "POSSIBLE CAUSES FOR EMISSIONS FAILURE" for further instructions.

### EMISSIONS TEST INFORMATION

### EVAPORATIVE SYSTEMS TEST INFORMATION

	2500	IDLE	LIMITS	RESULTS		PRESSURE	PURGE	FUEL CAP RESULTS
HC PPM	1477.1	871.7	1000.0	PASS	UNITS	INCHES/H <sub>2</sub> O	N/A	N/A
CO %	0.75	9.92	5.50	FAIL	LIMITS	N/A	N/A	
CO <sub>2</sub> %	9.1004	8.4617			READINGS	N/A	N/A	
RPM	2556	918	1350	OK	RESULTS	N/A	N/A	

### EQUIPMENT INSPECTION INFORMATION

- Catalytic Converter -
- Fuel Filler Restrictor -
- Air Injection System -
- Oxygen Sensor -
- Check Engine Light - N/A

### IF YOUR VEHICLE PASSED OR WAS ISSUED A WAIVER

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If you are renewing your registration by mail, follow the instructions regarding the renewal process located on the back side of your renewal notice. If you are renewing your registration in person, the Certificate of Emissions Control must accompany all supporting documents at the time of registration. If the Certificate of Emissions Control is lost, a new inspection is required at the owner's/operator's expense.

### IF YOUR VEHICLE FAILED THE INSPECTION

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If your vehicle failed its first inspection, you are entitled to one free reinspection within 10 calendar days if returned to the same independent inspection station. If the first inspection was performed at an Envirotest center, the reinspection can be performed at any one of Envirotest's centers. The information recorded on this "VEHICLE INSPECTION REPORT" is extremely valuable to a repair technician when having your vehicle repaired. The "VEHICLE REPAIR FORM", (VRF), located on the back must be completed by the person performing the repairs. The VRF must also accompany the vehicle at the time of reinspection. If your vehicle fails the reinspection you may be entitled to a waiver. Waiver eligibility information is available at the inspection stations or by calling the Department of Revenue at (303) 572-5603.

### POSSIBLE CAUSES FOR EMISSION FAILURE

#### HIGH CO READINGS

- A. Incorrect air fuel mixture
- B. Dirty air cleaner, choke or carb./fuel injection
- C. Carburetor float level improperly adjusted
- D. Inoperative air pump
- E. Diluted lubricating oil
- F. Soaked fuel evaporative canister



#### HIGH HC READINGS

- A. Defective points/electronic ignition
- B. Open plug wire or fouled spark plug
- C. Vacuum leak
- D. Incorrect air/fuel mixture
- E. Inoperative air pump
- F. Incorrect ignition timing

#### HIGH NO<sub>x</sub> READINGS

- A. Inoperative EGR system
- B. Incorrect ignition timing
- C. Incorrect air/fuel mixture
- D. Low octane fuel rating
- E. High combustion temperature
- F. Excessive carbon deposits

### OFFICIAL USE ONLY


 TST: 2 FEE: 15.00 LAT: 0.00 TAX: 0.00 DIS: 0.00  
 CSB: 0.00 CHK: 15.00 CDT: 0.00 CPN: 0.00  
 IN2: 00273 IN3: 05173 CYL: 8 RMON: 12 RYR: 1995 GVW: NVW: DSP: 4.3 FUL: GAS  
 TVFY: DAAF RVFY: 9769 VVFY: F16F SNV: SMON:  
 SYR: OCT: 12 REC: MAR: FORD MDL: MUSTANG VTY: P TRA: A DRV: R ABS: N 2STK: N  

 TRC: N WMB: DEX: N ECH: N EYR:  
 EFAW: HHC: 1152.4 HCO: 7.44  
 IHC: 1899.8 ICO: 11.44 AEW: 0 ATMP: 0 AWR: 0 ANSC: 0 ADIG: 0  
 ERES: F ORES: P PRES: IWFY: 6BEC RID: RCNT: 0







# VEHICLE INSPECTION REPORT

00871650

*Manager  
Voucher*

## STATE OF COLORADO RESULTS

Overall Result	Emissions	Evaporative Systems	Equipment Inspection	Smoke	CFC's	Recall	OBD Codes	Total Amount Paid
FAIL	FAIL			PASS	N/A		N/A	15.00

### VEHICLE INFORMATION

VIN	STATE	LICENSE PLATE	YEAR	MAKE	ODOMETER	
5R08K133254	CO	XXXX3254	1965	FORD	66020	
PROGRAM	INSPECTOR #	LANE #	STATION #	START TIME	END TIME	DATE
E	00083	03	5001E	10:10:51	10:20:02	30-DEC-1995

### CONSUMER INFORMATION

Your vehicle has failed to comply with required state regulations for emissions inspection. All items listed as failure must be addressed prior to your next inspection. See the box titled "IF YOUR VEHICLE FAILED THE INSPECTION" for further instructions. If your vehicle failed emissions, see the box titled "POSSIBLE CAUSES FOR EMISSIONS FAILURE" for further instructions.

### EMISSIONS TEST INFORMATION

### EVAPORATIVE SYSTEMS TEST INFORMATION

	2500	IDLE	LIMITS	RESULTS		PRESSURE	PURGE	FUEL CAP RESULTS
HC PPM	1172.2	592.0	1000.0	PASS	UNITS	INCHES <sup>3</sup> /H <sub>2</sub> O	N/A	N/A
CO %	1.44	9.43	5.50	FAIL	LIMITS	N/A	N/A	
CO <sub>2</sub> %	9.5105	9.2773			READINGS	N/A	N/A	
RPM	2499	1090	1350	OK	RESULTS	N/A	N/A	

### EQUIPMENT INSPECTION INFORMATION

- Catalytic Converter -
- Fuel Filler Restrictor -
- Air Injection System -
- Oxygen Sensor -
- Check Engine Light - N/A

### IF YOUR VEHICLE PASSED OR WAS ISSUED A WAIVER

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If you are renewing your registration by mail, follow the instructions regarding the renewal process located on the back side of your renewal notice. If you are renewing your registration in person, the Certificate of Emissions Control must accompany all supporting documents at the time of registration. If the Certificate of Emissions Control is lost, a new inspection is required at the owner's/operator's expense.

### IF YOUR VEHICLE FAILED THE INSPECTION

Your vehicle inspection results are shown on this "VEHICLE INSPECTION REPORT". If your vehicle failed its first inspection, you are entitled to one free reinspection within 10 calendar days if returned to the same independent inspection station. If the first inspection was performed at an Envirotest center, the reinspection can be performed at any one of Envirotest's centers. The information recorded on this "VEHICLE INSPECTION REPORT" is extremely valuable to a repair technician when having your vehicle repaired. The "VEHICLE REPAIR FORM", (VRF), located on the back must be completed by the person performing the repairs. The VRF must also accompany the vehicle at the time of reinspection. If your vehicle fails the reinspection you may be entitled to a waiver. Waiver eligibility information is available at the inspection stations or by calling the Department of Revenue at (303) 572-5603.

### POSSIBLE CAUSES FOR EMISSION FAILURE

#### HIGH CO READINGS

- A. Incorrect air fuel mixture
- B. Dirty air cleaner, choke or carb./fuel injection
- C. Carburetor float level improperly adjusted
- D. Inoperative air pump
- E. Diluted lubricating oil
- F. Soaked fuel evaporative canister



#### HIGH HC READINGS

- A. Defective points/electronic ignition
- B. Open plug wire or fouled spark plug
- C. Vacuum leak
- D. Incorrect air/fuel mixture
- E. Inoperative air pump
- F. Incorrect ignition timing

#### HIGH NOx READINGS

- A. Inoperative EGR system
- B. Incorrect ignition timing
- C. Incorrect air/fuel mixture
- D. Low octane fuel rating
- E. High combustion temperature
- F. Excessive carbon deposits

### OFFICIAL USE ONLY


 TST: 1 FEE: 15.00 LAT: 0.00 TAX: 0.00 DIS: 0.00  
 CSH: 15.00 CHK: 0.00 CDT: 0.00 CPN: 0.00  
 IN2: 10823 IN3: 12393 CYL: 8 RMON: 12 RYR: 1995 GVW: NVW: DSP: 4.3 FUL: GAS  
 TVFY: E781 RVFY: C146 VVFY: 1315 SNV: SMON:  
 SYR: OCT: 12 REC: MAK: FORD MDL: MUSTANG VTY: P TRA: A DRV: R ABS: N 2STK: N  

 TRC: N WMB: DEX: N ECH: N EYR:  
 EFAW: HHC: 1172.2 HCO: 1.44  
 IHC: 1097.0 ICO: 8.92  
 BRES: F ORES: P PRES: IWVFY: 2FA1





**INSURANCE IDENTIFICATION CARD STATE OF COLORADO**

**\***

**American Bankers Ins Co of FL**


**POLICY PROVIDES BODILY INJURY AND PROPERTY DAMAGE LIABILITY COVERAGES**

<b>NAME AND ADDRESS OF INSURED</b> RICHARD E SLAUGHTER 122 KOLAR COURT ERIE, CO 80516	<b>POLICY NUMBER</b> 2-27-31-94
	<b>EFFECTIVE DATE</b> 05/23/2009
	<b>EXPIRATION DATE</b> 05/23/2010

**APPLICABLE WITH RESPECT TO THE FOLLOWING MOTOR VEHICLE**

<b>YEAR</b>	<b>MAKE</b>	<b>VEHICLE IDENTIFICATION NUMBER</b>
1965	FORD CONV MUSTAN	5R08K133254

*THIS CARD SHOULD BE CARRIED  
IN THE VEHICLE AT ALL TIMES*

  
AUTHORIZED SIGNATURE





## **PRICE LIST**

**August 13, 1985**

**1964-73 MUSTANG/FORD  
1966-72 MOPAR  
1965-70 AMC  
IMPORTS  
(DUNLOP/GIRLING)**

**STAINLESS STEEL BRAKES CORP.**



# QUALITY CONTROL PROGRAM

In order to produce a large number of consistently safe Stainless Steel disc brake calipers, Stainless Steel Brakes Corporation maintains an ongoing quality control program.

**STAINLESS STEEL BRAKES CORPORATION** Quality Control Program consists of 100% inspection to assure part integrity, dial bore gage inspection of each cylinder to assure roundness and size and final Helium pressure and leak testing to catch those units which leak before (not after) shipment. (Pressure drop testing is inadequate because it cannot detect a minute leak that can result in a "loss of brake pedal.")

In addition, random samples are subject to extreme pressure testing. The pressure applied during this test is twice the maximum pressure that can be applied by power brakes during a panic stop. Thus this test verifies that the design is proper and that tolerance limits for that batch have not been violated. Only after a caliper has met our quality standards is it imprinted with our code — we started this practice in 1975.

The cost of the Quality Control Program is reflected in our selling price, but since public safety has no price tag, we consider this a price well worth the cost . . . **AND OUR CUSTOMERS APPRECIATE BRAKES THAT WORK CORRECTLY THE FIRST TIME** (as advertised).



**STAINLESS STEEL BRAKES CORP.**

**11470 Main Road / Clarence, N.Y. 14031**

**Call Toll Free 800-448-7722**

**In N.Y. (716) 759-8666**

®Stainless Steel Brakes Corp. 1985